


If you've just finished brake maintenance, the last thing you want happening to that HMMWV is brake failure! But it can happen to HMMWVs with serial numbers 299,999 and below if you don't give them the special attention they need.

Whenever you pull maintenance on any part of the brake system, make sure the loop clamp, NSN 5340-01-189-7640, that holds the brake line to the caliper on the right side of the vehicle is installed. If you don't, you could be super-sorry! Your HMMWV's brakes may not fail right away, but the jostling and rubbing could eventually lead to a long walk home.

You'll find the loop clamp in Chapter 7, Brake System (Field) Maintenance, of TM 9-2320-387-24-1 (Dec 97, w/Ch 6, Jun 09).



PS 728 12 JUL 13